www.himedialabs.com LIMENI Safety data sheet(SDS) According to Regulation (EC) No.1907/2006 Revision : 00002 Date of Revision : 26.03.2022 1 Identification of the substances/ mixture and of the company/ undertaking 1.1 **Product Identifiers** Product Number MCD120 Product Name Pseudomonas HiCynth[™] Agar (For Fluorescein) REACH Registration Number This product is a mixture. Reach registration number is not available for this mixture. 1.2 Relevant identified uses of the substance or mixture and uses advised against 1.2.1 Relevant identified uses Laboratory Chemicals, Analytical Purpose, Biochemical Analysis Details of the supplier of the safety data sheet 1.3 HiMedia Laboratories Private Limited Produced by Address C - 40,Road No.21Y,MIDC, Wagle Industrial Area, Thane(W), - 400 604, India Tel. No. +91-22-6147 1919/6116 9797 Fax No. : +91-22-61471920 Mail Id info@himedialabs.com Website : www.himedialabs.com 1.4 **Emergency Tel. No.** Emergency Tel. No. Please contact the regional HiMedia representation in your country

2 Hazards Identification

2.1 Classification of the substance or mixture *CLP Classification-Regulation (EC) No. 1272/2008[EU-GHS/CLP]*

Not a hazardous substance or mixture according to Regulation (EC) No.1272/2008.

2.2 Label elements

Labeling according to Regulation (EC) No.1272/2008

The product does not need to be labelled in accordance with EC directives or respective national laws.

2.3 Other Hazards

None

3 Composition/Information On Ingredients

3.2 Mixture

The components of this mixture need not be disclosed as per the regulations. All ingredients in this mixture are nonhazardous.

4 First Aid Measures

4.1 Description of first aid measures

General advice Consult a physician. Show this safety data sheet to the doctor in attendance. *If inhaled*

Page **1** of **6**

In case of skin contact Wash off with soap and plenty of water. Consult a physician. In case of eye contact Rinse immediately with plenty of water for at least 15 minutes. Consult a physician. if swallowed Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. 4.2 Most important symptoms and effects, both acute and delayed No data available. Indication of immediate medical attention and special treatment needed No data available. Indication of immediate medical attention and special treatment needed No data available. Sittble extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unswitcele extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unswitcele extinguishing media No data available. Sittble extinguishing media No data available. Sittble extinguishing media No data available. Sittble extinguishing media Sittble extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unswitces of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides Sittble extinguishing media No data available Sittble extinguishing media Sittble extinguishing medi		If breathed in, move person into fresh air. If not breathing, give artificial respiration. Consult a
 Wash off with soap and plenty of water. Consult a physician. In case of eye contact Rinse immediately with plenty of water for at least 15 minutes. Consult a physician. Hever give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. Most important symptoms and effects, both acute and delayed No data available. Indication of immediate medical attention and special treatment needed No data available Fire Fighting Measures Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray alcohol-resistant foam, dry chemical or carbon dioxide. Frecautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary Further information No data available Accid		physician.
In case of eye contact Rinse immediately with plenty of water for at least 15 minutes. Consult a physician. If swallowed Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. 4.2 Most important symptoms and effects, both acute and delayed No data available. 4.3 Indication of immediate medical attention and special treatment needed No data available 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. S.4 Further information No data available. S.5 Precautions for fire-fighters Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides S.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary S.4 Further information No data available Soluta available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory pro		-
Rinse immediately with plenty of water for at least 15 minutes. Consult a physician. if swallowed Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. 4.2 Most important symptoms and effects, both acute and delayed No data available. 4.3 Indication of immediate medical attention and special treatment needed No data available. 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Environmental precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.3 Accidental Release Measures 6.4 Accidental activations protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.3 Meethods and materials for ocntationment and cleaning up Soak up with inert adsorbent material an		
if swallowed Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. 4.2 Most important symptoms and effects, both acute and delayed No data available. Indication of immediate medical attention and special treatment needed No data available No data available 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potasium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to dos. Do not let product enter drains.		
Never give anything by mouth to an unconscious person. Rinse mouth with water. Consult a physician. 42 Most important symptoms and effects, both acute and delayed No data available. 4.3 Indication of immediate medical attention and special treatment needed No data available. 5 Fire Fighting Measures Statinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.1 Extinguishing media Suitable extinguishing media No data available. 7 Handling and Storage 7 Handling and Storage 7 Handling and Storage 7 Handling and Storage		
 hysician. 4.2 Most important symptoms and effects, both acute and delayed No data available. 4.3 Indication of immediate medical attention and special treatment needed No data available 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions 9 Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		•
 4.2 Most important symptoms and effects, both acute and delayed No data available. 4.3 Indication of immediate medical attention and special treatment needed No data available 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 4.3 Indication of immediate medical attention and special treatment needed No data available 5 Fire Fighting Measures 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	4.2	
S Fire Fighting Measures S.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. S.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides S.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary S.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1		No data available.
 Fire Fighting Measures Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary Further information No data available Accidental Release Measures Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. Reference to other sections For disposal see Section 13. Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	4.3	Indication of immediate medical attention and special treatment needed
 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		No data available
 5.1 Extinguishing media Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 Suitable extinguishing media Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evaluate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 		
 Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide. Unsuitable extinguishing media No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	5.1	
 Unsuitable extinguishing media No data available. Special hazards arising from the substance or mixture 		
 No data available. 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 5.2 Special hazards arising from the substance or mixture Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 Oxides of phosphorus, Potassium oxides, Magnesium oxides, Sulphur oxides 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	5.2	
 5.3 Precautions for fire-fighters Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	5.2	
 Wear self contained breathing apparatus for fire fighting if necessary 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	5.3	
 5.4 Further information No data available 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		-
 6 Accidental Release Measures 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	5.4	
 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		No data available
 6.1 Personal precautions, protective equipment and emergency procedures Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	6	Accidental Release Measures
 Wear respiratory protection. Avoid breathing vapours, mist or gas. Ensure adequate ventilation. Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 Evacuate personnel to safe areas. 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	•	
 6.2 Environmental precautions Prevent further leakage or spillage if safe to do so. Do not let product enter drains. 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 6.3 Methods and materials for containment and cleaning up Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	6.2	·
 Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		Prevent further leakage or spillage if safe to do so. Do not let product enter drains.
 containers for disposal. 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	6.3	Methods and materials for containment and cleaning up
 6.4 Reference to other sections For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		Soak up with inert adsorbent material and dispose of as hazardous waste. Keep in suitable, closed
 For disposal see Section 13. 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 		
 7 Handling and Storage 7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for 	6.4	
7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for		For disposal see Section 13.
7.1 Precautions for safe handling Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for	7	Handling and Storage
Avoid contact with skin and eyes. Avoid inhalation of vapour or mist. Normal measures for		• •
		-

7.2 Conditions for safe storage, including any incompatibilities

Page **2** of **6**

Store in cool place. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Recommended Storage Temperature : On receipt store between 10-30°C

7.3 Specific end uses

Apart from the uses mentioned in section 1.2 no other specific uses are stipulated.

8 **Exposure Controls/Personal Protection**

8.1 **Control parameters**

Components with workplace control parameters

8.2 **Exposure controls**

Appropriate engineering controls

Avoid contact with skin, eyes and clothing. Wash hands before breaks and immediately after handling the products.

Personal protective equipment

Hygiene measure

Immediately change contaminated clothing. Apply preventive skin protection. Wash hands and face after working with the product.

Eye/face protection

Tightly fitting saftey goggles; Faceshield (8-inch minimum). Use equipment for eye protection tested and approved under appropriate government standards such as NIOSH (US) or EN 166 (EU).

Skin protection

Handle with gloves. Gloves must be inspected prior to use. Use proper glove removal technique (without touching glove's outer surface) to avoid skin contact with this product. Dispose contaminated gloves after use in accordance with applicable laws and good laboratory practices. Wash and dry hands. The selected protective gloves have to satisfy the specifications of EU Directive 2016/425/EEC and the standard EN ISO 374-1/2016 derived from it.

Body protection

Complete suit protecting against chemicals. The type of protective equipment must be selected according to the concentration and amount of the dangerous substance at the specific workplace.

Respiratory protection

Where risk assessment shows air-purifying respirators are appropriate use a full-face respirator with multi-purpose combination (US) or type ABEK (EN 14387) respirator cartridges as a backup to engineering controls. If the respirator is the sole means of protection, use a full-face supplied air respirator. Use respirators and components tested and approved under appropriate government standards such as NIOSH (US) or CEN (EU).

Environment exposure controls

Do not empty into drains.

9 Physical and chemical properties

9.1 Information on basic physical and chemical properties Appearance Cream to yellow coloured homogeneous free flowing powder Odour No data available **Odour Threshold** No data available 6.80 - 7.20 pН No data available Melting/freezing point Initial boiling point and boiling range No data available

Flash point	No
Flammability (Solid, gas)	No
Vapour pressure	No
Relative density	N
Water Solubility	No
Partition coefficient: n-octanol/water	N
Autoignition Temperature	N
Viscosity	N
Explosive properties	N
Oxidizing properties	N
Vapour density	N
Thermal decomposition	N

No data available No data available

9.2 Other safety information No data available

10 Stability and	Reactivity
------------------	------------

- 10.1 Reactivity
- No data available 10.2 Chemical stability
 - No data available
- **10.3 Possibility of hazardous reactions** No data available
- **10.4** Conditions to avoid No data available
- 10.5 Incompatible materials
 - No data available
- **10.6 Hazardous decomposition products** Refer Section 5.2

11 Toxicological Information

11.1	Information on toxicological effects
	Acute toxicity
	No data available
	Skin corrosion/irritation
	No data available
	Serious eye damage/eye irritation
	No data available
	Respiratory or skin sensitisation
	No data available
	Germ cell mutagenicity
	No data available
	Carcinogenicity
	IARC: No component of this product present at levels greater than or equal to 0.1% is identified as
	probable, possible or confirmed human carcinogen by IARC.
	Reproductive toxicity

Page 4 of 6

No data available *Specific target organ toxicity- single exposure* No data available

Aspiration hazard No data available Potential Health Effects Inhalation REFER SECTION 2 Skin REFER SECTION 2 Eyes REFER SECTION 2 Ingestion REFER SECTION 2 Additional Information RTECS : No data available

12 Ecological Information

12.1 Toxicity

No data available

12.2 Persistence and degradability No data available

- **12.3 Bioaccumulative potential** No data available
- **12.4 Mobility in soil** No data available

12.5 PBT and vPvB assessment This substance or mixture contains no components considered to be persistent, bioaccumulating nor toxic (PBT) at levels of 0.1% or higher.

12.6 Other adverse effects No data available

13 Disposal Considerations

13.1 Waste treatments methods Product

Offer surplus and non- recyclable solutions to a licenced company. Contact a licenced professional waste disposal service to dispose off this material.

13.2 Contaminated packaging Dispose of as unused product.

14 Transport Information

14.1 UN-No

Page **5** of **6**

16	Other information
15.2	No data available Chemical Safety Assessment No data available
15.1	Safety health and environment regulations/legislation specific for the substance or mixture
15	Regulatory Information This safety data sheet complies with the requirements of Regulation (EC) No. 1907/2006
14.6	Special precautions for use No data available
14.5	Environmental hazards ADNR : No ADR : No IMDG : Marine Pollutant No IATA_C : No IATA_P : No RID : No
14.4	Packaging group ADNR : ADR : IATA_C : IATA_P : IMDG : RID :
14.3	Transport hazard class(es) ADNR : - ADR : - IATA_C : - IATA_P : - IMDG : - RID : -
	IATA_C : Not dangerous goods IATA_P : Not dangerous goods IMDG : Not dangerous goods RID : Not dangerous goods
14.2	ADNR : ADR : IATA_C : IATA_P : IMDG : RID : UN proper shipping name ADNR : Not dangerous goods ADR : Not dangerous goods
	ADNR : ADR : IATA_C : IATA_P : IMDG : RID :

Further Information

Copyright 2016 HiMedia Laboratories Pvt. Ltd.

The information given in this safety data sheet is believed to be correct yet does not claim to be all inclusive. This document is intended only as a guide for appropriate precautionary handling of the material by properly trained individuals, information here being commensurate with the present state of our knowledge regarding the manner and conditions of use, handling, storage or disposal. The information provided herein shall not be considered as guarantee of the properties of the product. HiMedia Laboratories, shall not be held liable for any damage resulting from improper handling or contact with the above product. Unless explicitly stated on the product or in any of the documentation accompanying the product, it is intended for research or testing purpose only and is not to be used for any other purpose.

Page 6 of 6